

Menu


HISTORY FILE MAP for year 2003

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



127.23:40 – 23:50 10m of 1024bps data lost. Telemetry processor failure (DC05 TLP FM unable to send output to MBX) at DSS-24. DR G102727 refers.